Service-Information

D-35 & D-50	January 27, 1984	Bulletin No. NA 0014

All freeze out plugs being installed in the D-35 and D-50 are now being made of stainless steel. When ordering these plugs, please use the following part numbers and correct your parts book accordingly:

45mm Ø — 11 11 1 761 140

40mm Ø — 11 12 1 761 143

38mm Ø — 11 12 1 761 142

36mm Ø — 11 12 1 761 141

We request that if a D-35 or D-50 is in your facility, a check be made for the proper plug and replaced if necessary. You may submit a warranty claim for reimbursement.

NOTE — If the complete engine serial number is not present on the claim form, the claim will be rejected.



BMW Marine
Service Dept.

V12 Engineering
Box 50, Ontario, Canada P0X 1C0
www.bmwmarine.net

Please route and initial before filing