Service-Information

Sail Auxiliary - D-7/D-12 Group No. 12 Fuses	June 4, 1981	Bulletin No. 12001 (1003)

Subject: Fuses

D-7/D-12 Electrical Diagrams

A printing error has occured on the wiring diagram and Owners Manuals for the D-7 and D-12.

The wiring diagram and Owners Manuals show two 8 amp fuses in the electrical system. The correct size fuse is 25 amps. We have been informed the engines have the 25 amp fuses installed on the engines.

Care should be taken when replacing the fuses that the 25 amp fuse is used and not the incorrect fuse as stated in the Owners Manual or wiring diagram.



Griff Fenton
Service Manager
BMW-NA MARINE
Montvale, NJ 07645

V12 Engineering
Box 50, Ontario, Canada P0X 1C0
www.bmwmarine.net

Please route and initial before filing

Service Manager	Parts Manager	Service Writer	Technicians