Service-Information

Sail Auxiliary - All Group No. 17 Tappet Clearance	April 30, 1980	Bulletin No. 17001 (1001)

Subject: Tappet Clearance for Intake and Exhaust

Engine	Clearance for Intake and Exhaust	
D-7	0.15mm	(0.006")
D-12	0.35mm	(0.014")
D-35	0.40mm	(0.016")
D-50	0.40mm	(0.016")

Please note this data, as it is otherwise stated in the Owners Manual. The maintenance is still to be performed every 100 hours or once yearly, per the Owners Manual.



V12 Engineering
Box 50, Ontario, Canada P0X 1C0
www.bmwmarine.net

Griff Fenton
Service Manager
BMW-NA MARINE
Montvale, NJ 07645

Please route and initial before filing

Service Mgr.	Parts Mgr.	Service Writ.	Technicians